

# GROVER CLEVELAND HIGH SCHOOL

## Upland Site Summary

---

*This Upland Site Summary was authored by New York City. The opinions, statements, and conclusions herein are solely those of New York City. They are not adopted by and should not be attributed to any other Person.*

### **SITE NAME: GROVER CLEVELAND HIGH SCHOOL**

**Address:** 21-27 Himrod Street, Queens, NY 11385

**Tax Lot Parcel(s):** Queens, Block 3363, Lot 1

**Latitude:** N 40° 42' 42.8"

**Longitude:** W 73° 54' 33.1"

**Regulatory Programs/Numbers/Codes:** NYR000158220

**Analytical Data Status:** ☐ Electronic Data Available ☒ Hardcopies only ☐ No Data Available

## **1 SUMMARY OF CONSTITUENTS OF POTENTIAL CONCERN (COPCS) TRANSPORT PATHWAYS TO THE CREEK**

### **Overland Transport**

This pathway is not complete, as the site is not adjacent to the waterway.

### **Bank Erosion**

This pathway is not complete, as the site is not adjacent to the waterway.

### **Groundwater**

The site is located approximately 1 mile from Newtown Creek and associated waterways. All of the documented work at the school was routine maintenance and construction work, as well as general school laboratory use. There is no documentation of any contaminant entering a pathway to Newtown Creek. All potential contaminants were handled pursuant to all relevant protocols and were appropriately removed from the facility and disposed of. There is no available groundwater quality information available for this site. There is insufficient evidence to determine whether groundwater reaches Newtown Creek. However, because there are no COPCs at the site that could reach the groundwater, this pathway is not complete.

### **Overwater Activities**

The site is not adjacent to Newtown Creek and associated waterways and therefore, has no overwater activities. This pathway is not complete.

### **Stormwater/Wastewater Systems**

Information related to stormwater and wastewater systems was not located for this site. All of the documented work at the school was routine maintenance and construction work, as well as general school laboratory use. There is no documentation of any contaminant entering a pathway to Newtown Creek. All potential contaminants were handled pursuant to all relevant protocols and were appropriately removed from the facility and disposed of. There is insufficient evidence to determine whether stormwater reaches Newtown Creek. However, because there are no COPCs at the site that could be transported via stormwater/wastewater, this pathway is not complete.

### **Air Releases**

Information related to air discharges was not located for this site. All of the documented work at the school was routine maintenance and construction work, as well as general school laboratory use. There is no documentation of any contaminant entering a pathway to Newtown Creek. All potential contaminants were handled pursuant to all relevant protocols and were appropriately removed from the facility and disposed of. There is insufficient evidence to determine whether air releases from a site 1 mile away reaches Newtown Creek. However, because there are no COPCs at the site, this pathway is not complete.

## **2 PROJECT STATUS**

No available files containing environmental investigations were identified for this site, other than manifests for disposal of hazardous waste.

## **3 SITE OWNERSHIP HISTORY**

- Respondent Member:      ☒ Yes   ☐ No

Owner	Occupant	Type of Operation	Years
New York City	New York City Department of Education	School	1930- present

#### 4 PROPERTY DESCRIPTION

This site consists of a four-story school building and athletic field. It is located approximately 1 mile from Newtown Creek. The only known hazardous chemical activities associated with the site arise from the transport of school laboratory chemicals from the site and asbestos, lead, and PCBs remediation at the site (see attached manifests). The chemicals used in the school laboratory are standard for high school science laboratories (such as hydrochloric acid, sodium hydroxide, mercury nitrate, etc.), and their proper removal from the facility for disposal is documented by waste manifests.

#### 5 CURRENT SITE USE

The site has been used as a school since 1930.

#### 6 SITE USE HISTORY

The site has been used as a school since 1930.

#### 7 CURRENT AND HISTORICAL AREAS OF CONCERN AND COPCs

##### Uplands

Reviewed records did not indicate upland areas of concern.

**Overwater Activities**    ☐ Yes   ☒ No

This site is not adjacent to Newtown Creek or associated waterways.

##### Spills

Reviewed records did not indicate current or historical spills.

#### 8 PHYSICAL SITE SETTING

No site specific geologic or hydrogeologic information is available for the site. The following information is based on regional conditions in the Brooklyn/Queens area.

The surface aquifer is typically contained with the upper glacial deposits and the lower portion of the anthropogenic fill layer. Depth to groundwater varies from a few feet to about 30 ft bgs in the historical data review area. Shallow groundwater generally flows towards and discharges to Newtown Creek (Misut and Monti 1999).

## 9.1 Soil

- **Soil Investigations**      ☐ Yes   ☒ No
- **Bank Samples**        ☐ Yes   ☐ No   ☒ Not Applicable
- **Soil Summary**

There is no evidence of soil contamination and no reason to believe that there is soil contamination on this site.

## 9.2 Groundwater

- Groundwater Investigations ☐ Yes ☒ No

- **NAPL Presence (Historical & Current)** ☐ Yes ☒ No
- **Dissolved COPC Plumes** ☐ Yes ☒ No
- **Visual Seep Sample Data** ☐ Yes ☐ No ☒ Not Applicable
- **Groundwater Summary**

The site is located approx. 1 mile away from Newtown Creek and associated waterways. There is no available groundwater quality information available for this site.

### 9.3 Surface Water

- **Surface Water Investigation** ☐ Yes ☒ No

Information related to surface water was not found in reviewed documents.

- **General or Individual Stormwater Permit (Current or Past)** ☐ Yes ☒ No
- **Do other non-stormwater wastes discharge to the system?** ☐ Yes ☒ No
- **Stormwater Data** ☐ Yes ☒ No

Information related to stormwater and wastewater systems was not located for this site.

### 9.4 Sediment

- **Creek Sediment Data** ☐ Yes ☐ No ☒ Not Applicable
- **Sediment Summary**

### 9.5 Air

- **Air Permit** ☐ Yes ☒ No
- **Air Data** ☐ Yes ☒ No
- **Air Summary**

Information related to air emissions was not found in reviewed documents.

## 10 REMEDIATION HISTORY (INTERIM REMEDIAL MEASURES AND OTHER CLEANUPS)

The attached manifests reflect the disposal of both hazardous and/or regulated materials: laboratory chemicals (such as hydrochloric acid, mercury, and ethyl alcohol), lead, PCBs, and asbestos. All non-laboratory wastes were generated as a result of capital improvement projects at the school, the scope of which is developed by New York City School Construction Authority ("SCA"). These wastes are generated from a number of different sources that are identified by SCA. Specialty contractors are hired to remove materials identified during the SCA survey that is regulated by federal, state and local regulators. All

material is properly disposed of at approved disposal facilities and the manifests are received and placed in the project file.

The attached PCB manifest, documenting a removal of PCB solid material/PCB debris, is likely associated with building caulking material. In those instances when the concentration of PCBs requires special provisions for disposal, the material is handled as described above. The natural attenuation of PCBs make them relatively immobile in the environment.

It appears that the other types of wastes in the attached manifests are related to building materials that were properly contained and disposed of during construction activities.

There are no areas of concern for this school because all of the documented work was routine maintenance and construction work, as well as general school laboratory use. There is no documentation of any contaminant entering a pathway to Newtown Creek. All potential contaminants were handled pursuant to all relevant protocols and were appropriately removed from the facility and disposed of.

## **11 BIBLIOGRAPHY / INFORMATION SOURCES**

- Project-Specific References  
DOE and SCA, Assorted waste manifests and bills of lading.

## **12 ATTACHMENTS**

**Figures:** None

**Tables:** None

# GROVER CLEVELAND HIGH SCHOOL Upland Site Summary

**Table 1**

## Potential Areas of Concern and Transport Pathways Assessment – Grover Cleveland High School Site

Potential Areas of Concern	Media Impacted					COPCs															Potential Historic or Current Complete Pathway				
	Surface Soil	Subsurface Soil	Groundwater	Catch Basin Solids	River Sediment	TPH			VOCs			SVOCs	PAHs	Phthalates	Phenolics	Metals	PCBs	Herbicides and Pesticides	Dioxins/Furans	Overland Transport	Groundwater	Direct Discharge – Overwater	Direct Discharge – Storm/Wastewater	Discharge to Sewer/CSO	Bank Erosion
						Gasoline-Range	Diesel – Range	Heavier – Range	Petroleum Related (e.g., BTEX)	VOCs	Chlorinated VOCs														
Description of Areas of Concern																									
No areas of Concern	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

**Notes:**

√ - COPCs are/were present in Areas of Concern having a current or historical pathway that is determined to be complete or potentially complete

? - There is not enough information to determine if COPC is/was present in Area of Concern or if pathway is complete

-- - Current or historical pathway has been investigated and shown to be not present or incomplete

COPCs – Constituents of Potential Concern

BTEX - Benzene, toluene, ethylbenzene, and xylenes

PAHs - Polycyclic aromatic hydrocarbons

SVOCs - Semi-volatile Organic Compounds

TPH - Total Petroleum Hydrocarbons

VOCs - Volatile Organic Compounds